

CITROEN AX

pag

1.1 cat. Single-point Weber G6	<u>2</u>
1.4 cat. Single-point Bosch '94	<u>3</u>
1.4 GTI cat. iniez. Multipoint	<u>4</u>

CITROEN BERLINGO

1.1 cat. Single-point Bosch	<u>5</u>
1.4 cat. Multipoint I.A.W. 1.40AP	<u>6</u>

CITROEN SAXO

1.1 cat. Single-point Bosch Motronic MA3.1	<u>7</u>
1.4 cat. Multipoint I.A.W. 1.40AP	<u>8</u>
1.6 8V cat. Mpi Bosch Motronic	<u>9</u>
1.6 Mpi cat. Iaw 1AP.41	<u>10</u>

CITROEN XANTIA

1.6 cat. iniez. Marelli I.A.W. 8P	<u>11</u>
1.8 cat. iniez. Bosch Motronic MP5.1	<u>12</u>
1.8 8V cat. 97' Mpi Iaw 1AP20	<u>13</u>
1.8 16V cat. iniez. Bosch Motronic MP5.1.1	<u>14</u>
2.0 cat. iniez. Marelli I.A.W. 8P	<u>11</u>
2.0 16V cat. Multipoint	<u>15</u>
2.0 16V cat. iniez. Bosch Motronic MP5.1.1	<u>14</u>

CITROEN XM

2.0 iniez. L-jetronic	<u>16</u>
2.0 iniez. Marelli	<u>17</u>

CITROEN XSARA

1.4 cat. Mpi Iaw 1AP.40	<u>18</u>
1.6 8V cat. Mpi Bosh Motronic	<u>19</u>
1.8 16V cat. Mpi Sagem	<u>20</u>

CITROEN ZX

1.4 cat. Single-point Bosch '93	<u>21</u>
1.4 cat. Single-point Bosch '94	<u>22</u>
1.4 cat. Single-point Weber G6	<u>23</u>
1.4 cat. iniez. MPI '97	<u>24</u>
1.6 cat. Single-point Weber G6	<u>23</u>
1.6 cat. MPI '95	<u>25</u>
1.8 cat. MPI	<u>26</u>

CITROEN JUMPI

pag

1.6 cat. Single-point Bosch 204	<u>27</u>
CITROEN VARIE - 1	<u>28</u>
CITROEN VARIE - 2	<u>29</u>
CITROEN VARIE - 3	<u>30</u>